

NUTCRACKERS
 GINGERBREAD
 CANDY

METAL STAMPINGS &
 PEWTER CASTINGS

C BEFORE # = CASTING
 * = DOUBLESIDED



3537
 COL: 1,2



3536
 COL: 1,2



3517
 COL: 1,2



C3621
 COL: 1,2,7



*C3651
 COL: 1,2,7



CANDLE
 C3610
 COL: 1,2,7



3526
 COL: 1,2,3



3525
 COL: 1,2,3



*C3624
 COL: 1,2



*C3587
 COL: 1,2,3



KISS
 *C3588
 COL: 1,2,3



8064
 COL: 1,2,3



3508
 COL: 1,2,3



C3573
 COL: 1,2,3



C3583
 COL: 1,2,3



3510
 COL: 1,2,3

W/HOLE



3511
 COL: 1,2,3

W/HOLE



3662
 COL: 1,2,3

NO HOLE



3663
 COL: 1,2,3

NO HOLE



3515
 COL: 1,2,3

WITH HOLE



3514
 COL: 1,2,3

WITH HOLE



3661
 COL: 1,2,3

NO HOLE



3660
 COL: 1,2,3

NO HOLE